

沙田 302 管理 有 限 公 司

S.T. 302 Management Limited

地址：新界沙田安景街 19 至 21 號地下

電話：2646 1859 傳真：2637 6131

本公司檔號: ST302/NTT/056/18/PS

致：百利閣 B 及 C 單位各業戶

通 告

有關:外牆排水喉管滲漏事宜

本處發現百利閣某 B 或 C 單位天井不時有疑似肥皂泡沫的水從上層浴室位置外牆灑下，懷疑是有個別牆身排水喉管損壞所致。此情況不但影響屋苑居住環境衛生，亦對其他住戶造成嚴重滋擾。因此，敬請 各業戶除定期檢查所屬排水設施外，如發現外牆任何排水設備有滲漏情況，請馬上聯絡管理處，以便本處能盡快通知所屬單位維修。

多謝合作！

碧濤花園第一期管理處

2018 年 3 月 7 日

Date : 7th March, 2018

To : All Residents of Flat B and C of Bellevue Court

NOTICE

Re: External walls drainage facilities leaks problem

It has come to our attention that a lot of soap water sprinkled from height (outside the bathroom of Flat B or C at Bellevue Court) frequently. It was suspected that some drainage facilities at external walls have damaged. The aforesaid situation not only affect environment hygiene of the building, but also cause seriously nuisance to others. As such, residents are requested carrying out periodical checking. If you find any water seepage problem from drainage system at external wall of the building, please notify management office for our further handling.

Thank you for your co-operation.



Management Office of Pictorial Garden Phase I